





PARTS LIST

MDS 700-4T


CNC Knee Mill with Tool Changer




Parts List



Parts List		
Item	Qty	Part Name
1	14	LINEAR RAIL PRESSER
2	4	LINEAR RAIL SADDLE
3	2	HOME LIMIT SWITCH
4	1	Z LIMIT SWITCH MOUNT
5	1	HEAD WIRING TERMINAL SUPPORT BRACKET LEFT
6	1	Z BALL SCREW NUT SPACER
7	1	Z BALL SCREW BASE MOUNT
8	1	Z MOTOR COUPLING AD2-56BDL64-19-22
9	3	SERVO MOTOR
10	3	BALL SCREW END NUT
11	1	HEAD TOP ACCESS PANEL
12	5	AIR PRESSURE VALVE 4V210-08 (By)
13	1	NECK CASTING
14	1	Z BALL SCREW NUT
15	1	Z BALL SCREW
16	1	Z BALL SCREW NUT HOUSING
17	1	Z ARMOR
18	2	Z LINEAR RAIL
19	1	NECK LOWER BRACKET
20	1	Z MOTOR COVER
21	1	AIR PRESSURE TERMINAL BLOCK 200M5F
22	1	HEAD INTERNAL WIRING SUPPORT BRACKET




Dept.	Technical reference	Created by John Shu	1/16/2020	Approved by
		Document type		Document status
		Title MDS 700-4T NECK PARTS LIST		DWG No.
		Rev.	Date of issue	Sheet 1/1




Parts List		
Item	Qty	Part Name
1	1	X LEFT COVER
2	1	X BALL SCREW MOUNT PLATE
3	3	BALL SCREW END NUT
4	3	BALL SCREW END SPACER RING FB4530
5	3	BALL SCREW SUPPORT BEARING
6	4	ANGULAR CONTACT BALL BEARING S7205 GB 292-94
7	2	BALL SCREW BEARING RING CAP
8	1	X BALL SCREW (7536)
9	2	X LIMIT DOG MOUNT
10	2	X HOME LIMIT DOG
11	1	E4 X TABLE 1270x254 XK7526
12	2	BALL SCREW NUT FD3208
13	1	BALL SCREW DEEP GROOVE BEARING 6205 GB 276-94
14	1	MOTOR COUPLING
15	1	X MOTOR MOUNT PLATE
16	3	SERVO MOTOR
17	1	X MOTOR COVER

Dept.	Technical reference	Created by John Shu	1/16/2020	Approved by
		Document type	Document status	
		Title MDS 700-4T TABLE PARTS LIST	DWG No.	
		Rev.	Date of issue	Sheet 1/1

Parts List		
Item	Qty	Part Name
1	2	TABLE SIDE DOOR
2	1	TABLE TOP ENCLOSURE
3	1	TABLE FRONT DOOR R (1)
4	2	TABLE DOOR HANDLE
5	1	TABLE FRONT DOOR L



Dept.	Technical reference	Created by John Shu	1/16/2020	Approved by
		Document type	Document status	
		Title	DWG No.	
		MDS 700-4T TABLE GUARD PARTS LIST	Rev.	Date of issue
			Sheet	1/1



12345678

A


B

C

D

E

F



Parts List

Item	Qty	Part Name
1	4	ATC CYL SDAS_50x5050_b
2	4	ATC CYL BASE
3	4	ATC CYL ROD SCREW
4	4	ATC CYL ROD NUT SDAD_40 M14x1.5
5	4	ATC CYL ROD ATTACHMENT
6	8	ATC CYL BLOCK
7	4	ATC ARM SHOULDER MOUNT
8	20	ATC ARM SHOULDER PIN
9	4	ATC ARM BICEP
10	4	ATC ARM CLAW BASE
11	4	ATC ARM CLAW
12	4	ATC ARM TRICEP
13	4	BT40 TOOL HOLDER
14	4	ATC CYL ROD SDAS_50x5050_r
15	4	BT40 TOOL PULL STUD
16	1	ATC PLATFORM
17	4	ER25 COLLET

A

B

C

D

E

F

Dept.	Technical reference	Created by John Shu	1/16/2020	Approved by
		Document type		Document status
		Title MDS 700-4T ATC PARTS LIST		DWG No.
			Rev.	Date of issue
				Sheet 1/1



MACH

MACHINE TOOLS

PRECISION MACHINE TOOLS · SALES · SERVICE · SUPPORT

UK & EUROPE

European Head Office

Units 1-3 Chapel Lane,
Clay Hill, Fishponds,
Bristol BS5 7EY,
United Kingdom

T +44 (0) 117 965 2706

E info@machmt.co.uk

NORTH AMERICA

US Office

200 Republic Ave,
Joliet, IL 60435,
USA

T +1 313 489 9667

E sales@machmt.com

ASIA

Asia Office

1 F.-A1, No. 50-26,
Shanzhuhu Rd,
Qionglin Township,
Hsinchu County,
Taiwan 307005

E sales@machmt.com

www.machmt.com